

ency

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

RE: AKRON AIRDOCK
31100203*AX
SUMMIT

of the Akron Airdock. The physical layout of the property. The Akron Airdock when in operation. As this facility does not discharge any water is the only regulated facility that has a multimillion dollar clean-up of the facility to remove PCB (Arochlor) contamination of the roof and sides

outlined the work that has been done as the surrounding pavement is under an NPDES permit, 601, 602, and 603. Outfall 603 is represented by 603. Outfall 603 is the storm sewer is identified in

information. If you should have any