
ONE PART IN PLASTIC BAG WITH STIFFENER

■ 3.5 MARKING (Unless otherwise specified in the contract or Purchasing Document use the following criteria)

3.5.1 Unit Package Marking

Label or mark each package to show at least the part number per contracting document and supplier identity. If this data is readily visible and legible on each part inside the unopened container, the labeling or marking requirement is waived. When packages contain thermal control parts, label each package per P-